



# SAFETY RECALL NOTICE

## QUICK-RELEASE MECHANISMS

### Hazard:

Front-wheel quick-release cam levers that are improperly adjusted or left open during riding and do not meet the #2 Pencil Test below may potentially interfere with the front disc brake rotor, which could result in the rider losing control and sustaining serious personal injuries.

This is a Safety Recall Notice regarding a group of bicycle brands listed below. Only bicycles equipped with front-wheel quick-releases and disc brakes are potentially affected. If the distance between the leading edge of the cam lever in its most open position and the disc rotor is less than 6 millimeters, which is the equivalent of the width of a standard #2 pencil (the “#2 Pencil Test”), your quick-release mechanism needs to be replaced. Please visit [www.quickreleaserecall.com](http://www.quickreleaserecall.com) for a video demonstration of the #2 Pencil Test.



Access	Haro
Breezer	Jamis
Cannondale	Norco
Civia	Novara
Diamondback	Raleigh
Felt	Ridley
Fuji	SE Racing
Giant	Specialized
GT	

### Remedy:

Stop riding the affected bicycle immediately and bring it to an authorized retailer of your bicycle’s brand, which will replace the affected quick-release free of charge. For any inquiries, please go to [www.quickreleaserecall.com](http://www.quickreleaserecall.com), click on the brand of your bicycle, and proceed from there.

### For More Information:

Please direct questions to your authorized local retailer, go to your brand’s website or watch the video at [www.quickreleaserecall.com](http://www.quickreleaserecall.com)



# SAFETY RECALL NOTICE



Post until 01/31/2016